

**DEVELOPING A MODEL TO PREDICT THE  
PROPAGATION OF SULFIDE STRESS CORROSION OF  
STEEL USED FOR PETROLEUM PIPELINES**

M.B.A. Deemantha

198044

Degree of Master of Science

Department of Materials Science and Engineering

University of Moratuwa,

Sri Lanka

March 2021

**DEVELOPING A MODEL TO PREDICT THE  
PROPAGATION OF SULFIDE STRESS CORROSION OF  
STEEL USED FOR PETROLEUM PIPELINES**

M.B.A Deemantha

198044

Thesis/Dissertation submitted in partial fulfillment of the requirements for the degree  
Master of Science

Department of Materials Science and Engineering

University of Moratuwa,

Sri Lanka

March 2021

## DECLARATION

I declare that this is my own work and this thesis does not incorporate without acknowledgement any material previously submitted for a degree or Diploma in any other University or institute of higher learning and to the best of my knowledge and belief it does not contain any material previously published or written by another person except where the acknowledgement is made in the text.

Also, I hereby grant to University of Moratuwa the non-exclusive right to reproduce and distribute my thesis/dissertation, in whole or in part in print, electronic or other medium. I retain the right to use this content in whole or part in future works (such as articles or books).

Signature: *UOM Verified Signature*

Date: 2021.11.09

The above candidate has carried out research for the Master's thesis under my supervision.

Name of the supervisor: Dr. G.I.P. De Silva

Signature of the supervisor: *UOM Verified Signature*

Date 2021.11.09

## ABSTRACT

Sulfide stress corrosion (SSC) is a deleterious type of corrosion that is abundant in petroleum refineries. SSC easily attacks oil country tubular goods (OCTG) in petroleum refineries. The main factors that affect SSC can be identified as the pressure/tensile stress applied on the metal, H<sub>2</sub>S concentration and time period. It can be identified that the environmental conditions of petroleum refineries provide optimum conditions for the initiation and propagation of SSC. Therefore petroleum refinery plants conduct time-basis routine inspections to detect the sulfide stress corrosion. When a severe corrosion is detected at an inspection routine, pipelines are required to be replaced. The unusual behavior of the propagation of SSC cracks may lead drastic failures before it is identified through an inspection routine. Therefore the petroleum industry is expecting to use an accurate model that can predict the initiation and propagation of sulfide stress corrosion. However, the mechanism of SSC has not been clearly revealed yet.

The principle aim of this study is developing a model that can predict the propagation of depth of sulfide stress corrosion in API 5L Grade B steel as a function of applied load (tensile load), pH value and time duration. API 5L Grade B steel was procured from Sri Lanka petroleum corporation as a seamless pipe. The model has been established based on the experimental values of depth of sulfide stress corrosion under different predetermined test environmental conditions kept within the pH value of 2.7 – 3.5, applied load of 400 – 800 N and time duration of 15 – 45 days. The depth of sulfide stress corrosion was measured using the scanning electron microscope images of cross sections of corroded steel specimens. The temperature and the pressure of the test environments were maintained at 24±3 °C and 1 atm respectively. Further, the model was validated by another data set obtained within the aforementioned, same ranges of parameters. All the laboratory experiments were conducted in accordance with ANSI/NACE TM0177-2016 standard test method.

In addition to the development of the model, the propagation behavior of SSC was investigated under the above mentioned different test environmental conditions. The microstructures that were observed through scanning electron microscope (SEM) and

SEM/EDAX elemental profile plots were obtained to investigate the Sulfur distribution within the crack.

According to the experimental results, it was able to develop a model that predicts the propagation of depth of sulfide stress corrosion. The model prediction values were in good agreement with the experimental values. However model tends to underestimate the depth of corrosion values when time duration closes to 30 days. Since the model has been constructed and validated within the pH value from 2.7 to 3.5, applied loads from 400 N – 800 N and time durations from 15 days to 45 days, the model is expected to be given the accurate predictions only within the aforementioned test environmental conditions.

The SEM images of cross sections of corroded specimens showed that crack initiation occurred after 15 days at all different test environmental conditions. Further, crack propagation occurred transversely, developing branches through the cross section until 30 days of time duration and the behavior of the propagation of crack was completely changed at 45 days of time duration.

## **ACKNOWLEDGEMENT**

This work is not achieved only by myself, but it is an achievement I had through supports of numerous individuals. First and foremost I would like to express my deepest gratitude to my supervisor Dr. G.I.P. De Silva. He provided me with a great opportunity to join with this research project and has always been supportive to accomplish my objectives. His unstinting guidance and constructive feedback improved my research ability and professional skills.

I would like to thank Prof M. Narayana and Dr. (Mrs.) N.M.V.K. Liyanage for their immense support and academic push throughout the evaluation procedure. Next, I would like to thank Ceylon Petroleum Corporation for providing steel samples for research works.

Further, I would like to thank all academic and nonacademic staff of department of materials science and engineering, University of Moratuwa for supporting me to conduct my research works in a better academic environment. Lastly, I convey my love and gratitude to my parents for their constant support.

# TABLE OF CONTENTS

<b>1 INTRODUCTION.....</b>	<b>1</b>
1.1 Research background and problem statement .....	1
1.2 Objectives .....	4
<b>2 LITERATURE SURVEY .....</b>	<b>5</b>
2.1 Mechanisms of SSC cracks propagation .....	5
2.2 Mackinawite .....	10
2.3 Propagation of sulfide stress crack .....	13
2.4 Identification of sulfide stress cracks .....	16
2.5 Comparison of models.....	20
2.6 Factors effecting sulfide stress cracking. ....	23
<b>3 EXPERIMENTAL PROGRAM.....</b>	<b>30</b>
3.1 Materials .....	30
3.2 Experimental setup – Test conditions in the corrosive vessel .....	31
3.2.1 Fabrication of the test vessel and specimens .....	31
3.2.2 Test solution.....	32
3.2.3 Test specimens.....	33
3.2.4 Sample holder/Specimens fixture .....	33
3.2.5 Determination of the applied load (tensile) values. ....	34
3.2.6 Final experimental setup.....	34
3.2.7 Experimental conditions. ....	35
3.2.8 Determination of depth of corrosion by SEM observations. ....	36
3.2.9 SEM/EDAX analysis of SSC cracks .....	38
3.2.10 Development of the statistical model.....	38
<b>4 RESULTS AND DISCUSSION .....</b>	<b>41</b>
4.1 Implementation of the model.....	41
4.2 Validation of the model .....	47
4.2.1 Validation of the model based on the predetermined test environmental conditions.....	47
4.2.2 Validation of the model based on the random test environmental conditions.....	50
4.3 Limitations of the model .....	51
4.4 Interpretation of behavior of SSC by SEM/EDAX analysis .....	52
<b>5 CONCLUSIONS.....</b>	<b>60</b>
<b>6 RECOMMENDATIONS.....</b>	<b>61</b>
<b>7 REFERENCES.....</b>	<b>62</b>

## LIST OF FIGURES

Figure 2. 1 : Mackinawite crystal structure.....	11
Figure 2. 2 : Mackinawite crystal lattice located on a ferritic iron surface.....	12
Figure 2. 3: Mackinawite structure with additional cations intercalated in the structure .....	13
Figure 2. 4: Different reaction pathways for Mackinawite .....	14
Figure 2. 5: SEM image ruptured corrosion product layer. ....	15
Figure 2. 6: A corroded inner surface of the control valve body, (a) near the seat ring and (b) near the valve’s flange.....	17
Figure 2. 7: A cross section of valve body base metal after 3 years of service in wet H <sub>2</sub> S environment (a) Crack emanating from inner surface of the valve’s surface (b) surface of the valve’s flange. ....	17
Figure 2. 8: SEM images of SSC cracks in A216 steel (a) main crack and (b) branched cracks. Cracks propagated from inner surface to the base metal. ....	18
Figure 2. 9: SEM images of the cross-section plane of specimens and the selected areas for EBSD analysis .....	19
Figure 2. 10: The experimental and prediction corrosion rate vs. time under the conditions of total pressure p=1 bar, H <sub>2</sub> S gas concentration from 0.1% to 10%, T 80°C, reaction time of 1 hour and 24 hours, pH 5.0-5.5, and velocity 0rpm .....	21
Figure 2. 11: Comparison of corrosion rate predictions with experimental results in the solution purged with different partial pressures of H <sub>2</sub> S gas in the H <sub>2</sub> S/CO <sub>2</sub> gas mixture. Data taken from Lee [34]. ....	22



Figure 2. 12: Comparison of corrosion rate predictions with experimental results in the solution purged with different partial pressures of H <sub>2</sub> S gas in the H <sub>2</sub> S/CO <sub>2</sub> gas mixture. Data taken from Choi et al [35].....	22
Figure 2. 13: SSC failure windows for pH and H <sub>2</sub> S partial pressure (Tale (2014) redrawing from Morana and Nice (2009)): a) P-110; b) Q-125; c) Grade 140; and d) Grade 150.....	25
Figure 2. 14: Relation between applied stress and fail time .....	26
Figure 2. 15: (a) and phase angle (b) diagrams of API 5L X65 and API 5L X80 steels in de-aerated solution A, NACE TM0284 (2011), without and with H <sub>2</sub> S saturation. Experimental Procedure 1.....	27
Figure 2. 16: (a) and phase angle (b) diagrams for the API 5L X65 steel during 24h immersion in de-aerated solution A, NACE TM0284 (2011), saturated with H <sub>2</sub> S, sour medium. Procedure 2. ....	27
Figure 2. 17: (a) and phase angle (b) diagrams for the API 5L API 5L X80 steel during 24h immersion in de-aerated solution A, NACE TM0284 (2011), saturated with H <sub>2</sub> S, sour medium.....	28
Figure 2. 18: Loading stress vs. time to failure plots for the inertia friction welds and AISI 4137-H steel .....	29
Figure 3.1: Test vessel.....	32
Figure 3.2: Dimensions of the test specimen .....	33
Figure 3.3 : Steel sample holder.....	35

Figure 3.4 : Final Experimental setup.....	35
Figure 3.5: Three transverse cuts of a specimen and obtaining average depth of corrosion .....	37
Figure 3.6: Low speed precision cutting machine .....	38
Figure 3. 7 : Interface of the data view of input of data.....	38
Figure 3. 8 : Interface of the variable view of input of data.....	39
Figure 4. 1: scatter plot of depth of sulfide stress corrosion Vs 1/applied load.....	42
Figure 4. 2: scatter plot of depth of sulfide stress corrosion Vs e <sup>pH</sup> load.....	43
Figure 4. 3: scatter plot of depth of sulfide stress corrosion Vs Time <sup>4.45</sup> load.....	43
Figure 4. 4: Histogram of frequency Vs Regression standardized residual .....	44
Figure 4. 5: Normal P-P plot of regression standardized residuals.....	46
Figure 4. 6: Scatter plot of standardized residuals Vs standardized predicted values .....	46
Figure 4. 7: Scatter plot of standardized residuals Vs unstandardized predicted values .....	47
Figure 4. 8: The comparison of model predicted values and experimental values of depth of sulfide stress corrosion at 27 °C and 1 atm under different test environmental conditions .....	48
Figure 4. 9: comparison between model prediction values and the experimental results.....	50
Figure 4. 10: SEM image of the cross section of a specimen under the test conditions of pH value – 2.5, Load – 800 N, Time duration - 14 days.....	52
Figure 4. 11: SEM image of the cross section of a specimen under the test conditions of pH value = 3.5, applied load = 400 N and time duration = 15 days .....	53

Figure 4. 12: Elemental profile plot of the cross section of a specimen under the test conditions of pH value – 2.5, Load – 600 N, Time duration –15 days .....	54
Figure 4. 13: SEM image of the cross section of a specimen under the test conditions of pH value = 2.5, applied load = 400 N and time duration = 30.....	55
Figure 4. 14: Elemental profile plot of the cross section of a specimen under the test conditions of pH value – 3.5, Load – 600 N, Time duration – 30 days .....	55
Figure 4. 15: SEM image of the cross section of a specimen under the test conditions of pH value – 2.5, Load – 800 N, Time duration – 45 days .....	58
Figure 4. 16: SEM image of the cross section of a specimen under the test conditions of pH value – 3.5, Load – 800 N, Time duration – 45 days.....	59

## **LIST OF TABLES**

Table 3. 1: Chemical composition of API 5L Grade B.....	30
Table 3. 2: Mechanical and physical properties of API 5L Grade B steel.....	30
Table 3. 3 : Test environmental conditions.....	36
Table 4. 1: Test of normality.....	42
Table 4. 2: Pearson’s correlation matrix .....	44
Table 4. 3: Collinearity diagnostic tables.....	45
Table 4. 4 : Test environmental conditions given by numbers in Figure 4.8.....	48
Table 4. 5: Test environmental conditions given by numbers in Figure 4.9.....	50

Table 4. 6: Parameter ranges defined for the model at temperature 27 °C and the pressure

1 atm..... 52